Work Order	Source			Wo Part Desc	Amount	Tax	Freight	Tax On Freight
		Po No	Vendor Name					
00-07718-0	JE			JOURNAL ENTRY 1002027	1000.00			
00-07718-0	JE **			JOURNAL ENTRY 1002027	5000.00			
00-07718-0	JE				6000.00	0.00	0.00	0.00
00-07718-0	PJ	02-22354	TURBOCARE	PROVIDE ALL MATERIALS, SUPERVISION, LABO	-153697.05			
00-07718-0	PJ	02-22354	TURBOCARE	PROVIDE ALL MATERIALS, SUPERVISION, LABO	145340.00	8357.05		
00-07718-0	PJ				10734.00			
00-07718-0	PJ	02-22354	TURBOCARE	PROVIDE ALL MATERIALS, SUPERVISION, LABO	192140.00	11048.05		
00-07718-0	ΡJ	02-22354	TURBOCARE	PROVIDE ALL MATERIALS, SUPERVISION, LABO	-164000.00	-9430.00		
00-07718-0	PJ	02-22354	TURBOCARE	PROVIDE ALL MATERIALS, SUPERVISION, LABO	138400.00	6003.00		
00-07718-0	PJ	02-22354	TURBOCARE	PROVIDE ALL MATERIALS, SUPERVISION, LABO	34000.00	1955.00		
00-07718-0	PJ	02-22354	TURBOCARE	PROVIDE ALL MATERIALS, SUPERVISION, LABO	12800.00	736.00		
00-07718-0	** PJ				215716.95	18669.10	0.00	0.00
00-07718-0					221716.95	18669.10	0.00	0.00
					221716.95	18669.10	0.00	0.00
						10007.10	0.00	3.00

¹⁰ records listed.

Report Name: MO.COST.DETAIL.WITH.SUBS



CHICOPEE.

2140 WESTOVER ROAD

MA

01022-1057

PURCHASE ORDER

04 JAN 2002

VENDOR MUST SHOW P.O. NUMBER ON ALL INVOICES, BILL OF LADING. CORRESPONDENCE, AND ON PACKING LISTS IN EACH CONTAINER, TO INSURE PROMPT PAYMENT. CHARGES FOR TRANSPORTATION MUST BE SUPPORTED BY COPY OF FREIGHT BILL.

PURCHASE ORDER NO. VENDOR CODE REQUISITION NO 02-22354 3001 173417

01 0111 -00-

* * * S H I P T O * * *
INTERMOUNTAIN POWER SERVICE CORPORATION
850 W. BRUSH WELLMAN RD.

DELTA , UT 84624-9546

800-346-5462 OR 413-593-0500

CONFIRMING DO NON CONFIRMING X BEST WAY

TERMS NET 30

FOB POINT DESTINATION F/A

1 PAGE 2 NONE

QUANTITY ORDERED	UNIT	IPSC PART NO.	DESCRIPTION	ACCOUNT NUMBER	UNIT PRICE	EXTENSION
1	sv		LINE 1 PROVIDE ALL MATERIALS, SUPERVISION, LABOR, TOOLS, AND EQUIPMENT FOR VARIABLE CLEARANCE DIAPHRAGM AND REDUCED CLEARANCE SPILL STRIP INSTALLATION IN THE INTERMEDIATE PRESSURE TURBINE SECTION ON UNIT 2 DURING THE SPRING 2002 OUTAGE		179,340.00	179,340.00
1	sv		LINE 2 PROVIDE ALL MATERIALS, SUPERVISION, LABOR, TOOLS, AND EQUIPMENT FOR VARIABLE CLEARANCE DIAPHRAGM AND REDUCED CLEARANCE SPILL STRIP INSTALLATION IN THE INTERMEDIATE PRESSURE TURBINE SECTION ON UNIT 1 DURING THE SPRING 2003 OUTAGE		179,340.00	179,340.00
			ATTENTION: BOB HOGAN/KRISTEN SCHROEDER RCN/CLE			

- Invoices and correspondence may be mailed to Intermountain Power Service Corporation, 850 West Brush Wellman Rd., Delta, Utah, 84624-9546.
- 2. Acknowledgement is required if shipment will not be made within Five days.
- 3. Mark packages or items with IPSC part number and/or P.O. Line number. Show number on invoice and packing slip.
- 4. Vendor must furnish applicable material safety data sheets.

UTAH VENDORS	ARE TO	ADD	TO THE	INVOICE
ALL APPLICABLE	STATE.	AND	COUNT	/ TAXES

OUT OF STATE VENDORS, LICENSED TO COLLECT UTAH TAXES, ARE TO ADD TAX OF 6%.

UTAH TAXES WILL BE ACCRUED BY IPSC FOR OUT OF STATE VENDORS NOT LICENSED TO COLLECT LITAH STATE TAY

BUYER	
-------	--



PURCHASE ORDER

04 JAN 2002

VENDOR MUST SHOW P.O. NUMBER ON ALL INVOICES, BILL OF LADING. CORRESPONDENCE, AND ON PACKING LISTS IN EACH CONTAINER, TO INSURE PROMPT PAYMENT. CHARGES FOR TRANSPORTATION MUST BE SUPPORTED BY COPY OF FREIGHT BILL. PURCHASE ORDER NO.

VENDOR CODE REQUISITION NO 02-22354 3001 173417

SHIP TO INTERMOUNTAIN POWER SERVICE CORPORATION 850 W. BRUSH WELLMAN RD. DELTA , UT 84624-9546

800-346-5462 OR 413-593-0500

CONFIRMING DO I NON VITO	EST WAY	TERMS NET 30	FOR POINT DESTINATION F/A	2 PAGE 2	NONE


DUANTITY ORDERED	UNIT	IPSC PART NO.	DESCRIPTION	ACCOUNT NUMBER	UNIT PRICE	EXTENSION
			NOTE: TOTAL COST INCLUDES OPTION III, PARAGRAPH 1 OF VENDOR'S QUOTE, FOR AN ADDITIONAL \$9,600 PER UNIT FOR UPGRADED SPE COATED SPILL STRIPS FOR STAGES 9 THROUGH 14			
		·	**NOTE: THE ATTACHED REVISED ADDITIONAL GENERAL CONDITIONS, PART E, DIVISION E2, OF SPECIFICATIONS 45556 ARE MADE A PART OF THIS PURCHASE ORDER BY REFERENCE HEREIN**			
			SERVICE CONTRACT TERMS AND CONDITIONS (TC-100'S) ARE INCORPORATED IN THIS PURCHASE ORDER BY REFERENCE			
			*******ATTENTION IPSC WAREHOUSE****** THIS ORDER IS FOR A SERVICE AND NO MATERIAL WILL BE RECEIVED			
			DATE REQUIRED 02/21/02	тоти	AL COST	358,680.0

- 1, Invoices and correspondence may be mailed to Intermountain Power Service Corporation, 850 West Brush Wellman Rd., Delta, Utah, 84624-9546.
- 2. Acknowledgement is required if shipment will not be made within Five days.
- 3. Mark packages or items with IPSC part number and/or P.O. Line number. Show number on invoice and packing slip.
- 4. Vendor must furnish applicable material safety data sheets.

UTAH VENDORS ARE TO ADD TO THE INVOICE ALL APPLICABLE STATE, AND COUNTY TAXES.

OUT OF STATE VENDORS, LICENSED TO COLLECT UTAH TAXES. ARE TO ADD TAX OF 6%.

UTAH TAXES WILL BE ACCRUED BY IPSC FOR OUT OF STATE VENDORS NOT LICENSED TO COLLECT LITAL STATE TAY



BUYER

REVIEWED BY







CHICOPEE, MA

2140 WESTOVER ROAD

01022-1057

PURCHASE ORDER

04 JAN 2002 REVISED 06 MAY 2002 VENDOR MUST SHOW P.O. NUMBER ON ALL INVOICES, BILL OF LADING. CORRESPONDENCE, AND ON PACKING LISTS IN EACH CONTAINER, TO INSURE PROMPT PAYMENT. CHARGES FOR TRANSPORTATION MUST BE SUPPORTED BY COPY OF FREIGHT BILL.

PURCHASE ORDER NO. 02-22354 VENDOR CODE REQUISITION NO 173417

INTERMOUNTAIN POWER SERVICE CORPORATION

* * * * SHIP TO * * *

850 W. BRUSH WELLMAN RD. DELTA , UT 84624-9546

800-346-5462 OR 413-593-0500

CONFIRMING DO NON CONFIRMING X SHIP VIA BEST WAY

TERMS NET 30

FOB POINT DESTINATION F/A

1 PAGE 1 MAIL

JANTITY RDERED	UNIT	IPSC PART N O.	DESCRIPTION	ACCOUNT NUMBER	UNIT PRICE	EXTENSION
1	sv		· · · · · · · · · · · · · · · · · · ·		** PRICE	
			AND EQUIPMENT FOR VARIABLE CLEARANCE DIAPHRAGM AND REDUCED CLEARANCE SPILL STRIP INSTALLATION IN THE INTERMEDIATE PRESSURE TURBINE SECTION ON UNIT 2 DURING THE SPRING 2002 OUTAGE	00-07718-0		
			TO CLEAN UP RECORDS & TO ADJUST PO TO ACTUAL AMOUNT PAID. PO WAS ORIGINALLY \$179,340. INCREASE PO \$10,734 PER ADDITIONAL WORK ON INVOICE NO. 106864. INVOICE APPROVED BY DENNIS KILLIAN & GEORGE W. CROSS ON 05/3/02 RN/CLE			

- Invoices and correspondence may be mailed to Intermountain Power Service Corporation, 850 West Brush Wellman Rd., Delta, Utah, 84624-9546.
- 2. Acknowledgement is required if shipment will not be made within Five days.
- 3. Mark packages or items with IPSC part number and/or P.0. Line number. Show number on invoice and packing slip.
- 4. Vendor must furnish applicable material safety data sheets.
- 5. Add to invoice all applicable federal taxes.

UTAH VENDORS ARE TO ADD TO THE INVOICE ALL APPLICABLE STATE, AND COUNTY TAXES.

OUT OF STATE VENDORS, LICENSED TO COLLECT UTAH TAXES. ARE TO ADD TAX OF 6%,

UTAH TAXES WILL BE ACCRUED BY IPSC FOR OUT OF STATE VENDORS NOT LICENSED TO COLLECT UTAH STATE TAX

RALPH NEWBERRY 435-864-4414

BUYER

REVIEWED BY S. CHAPMAN

Spec. 45556

PART E - DIVISION E2

ADDITIONAL GENERAL CONDITIONS

1. <u>Performance</u>: Work completed during the outage on the high-pressure turbine section shall be guaranteed to produce an improvement in section efficiency equal to eighty (80) percent of recovered losses. The recovered losses shall be based on the calculated difference in steam path efficiency, as agreed upon by the Contractor and IPSC, between an opening and closing steam path audit.

IPSC will complete pre-outage performance tests to determine the performance level of the high-pressure turbine section. After the high-pressure section is opened, an opening steam path audit will be conducted by IPSC. The performance loss due to steam path deterioration will be determined by calculation. The types of deterioration that will be considered are, but not limited to, solid particle erosion, deposits, increased clearances, foreign object damage, and component surface roughness. Actual steam path repairs will be determined by IPSC following evaluation of the opening steam path audit.

Prior to closing the high-pressure section, a closing steam path audit will be conducted by IPSC to determine the recovered losses attributable to outage maintenance activities. The recovered losses will be calculated and agreed upon by the Contractor and IPSC.

2. Performance Tests: IPSC will conduct pre and post-outage performance tests with the intention of determining compliance with the performance guarantees. The tests will be conducted using plant instrumentation calibrated by IPSC, and by using design calculations agreed upon by the Contractor and IPSC where measurements are impractical. The tests will be conducted at valve wide open and corrected to design throttle conditions.

The general methods outlined in the ASME test code will be used as a guide for test procedures; however, code technicalities shall not void the validity of these tests. The Contractor shall have the right to witness the tests.

In addition to the above test procedures, IPSC may utilize a third party contractor to conduct ASME Performance Test Code tests (ASME PTC-6S) for the pre and post-outage testing. IPSC further reserves the right to use a third party contractor to conduct the opening and closing steam path audits. The results of the performance tests and steam path audits shall then be binding on the parties of this Contract.

All reasonable effort will be made to conduct the pre-outage performance tests within four (4) weeks before the start of the outage and the post-outage test within four (4) weeks of the initial startup following the outage.

3. <u>Guarantee</u>: The Contractor shall guarantee that the high-pressure turbine section shall meet the performance conditions as set forth in these Specifications.

If the field tests indicate that such performance conditions are not met, then IPSC shall be entitled to damages, excluding consequential damages, for such deficient performance. The damages for failing to meet the performance conditions as set forth in these Specifications shall be ten (10) percent of the Contract amount. It is agreed between the Contractor and IPSC that it would be impossible or extremely difficult to

determine actual damages for failing to meet the guaranteed performance and that the above agreed amounts are reasonable liquidated damages and do not constitute a penalty.

The Contractor shall repair or replace, f.o.b. contract delivery point, all defective materials and workmanship.

- 4. <u>Payment</u>: Payment will be made within thirty (30) calendar days after completion of outage and performance tests, and receipt of the invoice.
- 5. Regulations, Permits, Licenses, and Warrants: The Contractor shall comply with all applicable federal, state, and local regulations including, but not limited to, Federal and State Occupational Safety Health Administration (OSHA), as said regulations relate to this Contract. In addition, the Contractor shall ensure that all permits, licenses, and warrants relating to the Contract be acquired.
- 6. <u>Invoices</u>: Invoices shall be submitted in duplicate to Accounts Payable, Intermountain Power Service Corporation, 850 West Brush Wellman Road, Delta, UT 84624-9546.

Each invoice shall show the Contract number. In all cases, the amount of the applicable sales tax or use tax shall be separately stated on the invoice.

7. <u>Letters to IPSC</u>: All inquiries relating to these Specifications prior to award of the Contract shall be addressed to the Buyer.

After award of Contract, all letters pertaining to performance of the Contract shall be addressed as follows:

S. Gale Chapman President and Chief Operations Officer Intermountain Power Service Corporation 850 West Brush Wellman Road Delta, UT 84624-9546

Attention: Contract Administrator

Regarding Contract No. 02-45556

TERMOUNTAIN POWER SERVICE CORPORATION

REQUISITION FOR CAPITAL EQUIPMENT

PURCHASE AUTHORIZATION FOR EXPENSE ITEMS

arpose of Materials, Supplies or Services:

Suggested Vendor: Competitive Bid

Purchase variable clearance packing and reduced clearance soill strips for istaliation in the intermediate pressure turbine sections of both Unit I and init 2. This is identified Capital Project IGS01-17 for the 2001-02 and 002-03 budget

Date: /-4	02
Req./PA No:	173417
P.O. No: 6	2-22354
Vendor:	TURBO CARE
Terms: 8	5
FOB: 0/	
Ship Via:	8'
Cont. To: B	il Hagan/
	40

Del 2-21-02 Kristen Schroeler Account No. 001TGX-402 Work Order No. 00-7718-0 Project No. _____IGS 01-17

Qty	Unit	Description Seller or Noun Adjective Catalog # Manufacturer	Unit Cost	Extension
1	1	Unit 2: All materials, supervision, labor, tools, and equipment for variable clearance diaphragm and reduced clearance spill strip installation in the intermediate pressure turbine section during the Spring 2002 outage.		\$3 42,000.0 0
1	1	Unit 1: All materials, supervision, labor, tools, and equipment for variable clearance diaphragm and reduced clearance spill strip installation in the intermediate pressure turbine section during the Spring 2003 outage.		\$ 342.000.00
	MO	to The attacked Revised additional to	neral (onditions
		CFIVED mall a sort of the sushare	: 	
		order by relaxerable have		
		(2001 -		\$358,600 09
·	PUR	CHASING		\$3580
		TOTAL ESTIMATED COST		\$684,000.00

Contact D. Spence at 8449 or A. Niesen at 6482 with

Manuafly

Pa, Levised Specs

+ C's (100)

Tatal cart includes option III. Para (of vendor quate for an additional 4,600,00 Per unit far upgraded papel attips for styre (SPE Coated)

IP7_005211